| NIGHT INCIDENT | | 0-70 |
|---|---|--|
| Report | | A d v a n c e d Accelerator Applications A Novartis Company |
| Site | Oporto | 6 3. Jacob 1997 - 22 |
| Date and time | 2023-09-12 08:56 | <u>,</u> |
| Attended | | |
| Phone X Site | | |
| | | |
| Department Engineering | | |
| | | |
| | | |
| Yes X No | | |
| System | | |
| Synthesizers - FASTLAB2DUO | | |
| System description | | |
| | | |
| Describe the incident | | |
| A technician accidentally do a single run for calibration | | |
| Solved? | | |
| Yes X No | | |
| | | |
| Derived? | | |
| Yes No 🗙 | | |
| To whom? | | |
| Yes - Site Yes - Production manager manager | Yes - | P Others |
| | | |
| Who is other? | | |
| | | |
| Production affected? | | |
| No X Yes - Totally cancelled Yes - Partially can | ncelled Yes - Delayed | |
| Any comment? | | |
| | | |
| If possible, describe the solution | | |
| Was not a problem because we are using just one run of the | fastlab cassette | |
| The second | | |
| If possible, describe the root cause | | |
| | | |
| TotalTimeOfIntervention | | |