

NIGHT INCIDENT



Report

Site

Murcia

Date and time

2023-10-30 02:07

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

Cyclotron - H2 gas & circuit

System description

Describe the incident

The general manometer was in 0 bars

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

the manometer seems to had been miss configured , so or it was due was adjusted with the broken massflow pr that during massflow tests before to change it I moved it trying to face the gas flow

If possible, describe the solution

Adjust the manometer

If possible, describe the root cause

TotalTimeOfIntervention

60.0