

NIGHT INCIDENT

Report



Site

Oporto

Date and time

2023-10-23 02:03

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Synthesizers - TRASIS AIO

System description

Describe the incident

The technician inadvertently failed to set the pre-irradiation timer on time, causing a delay. Consequently, I received a call to verify if the irradiation duration was adequate.

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

'The technician inadvertently failed to set the pre-irradiation timer on time, causing a delay. Consequently, I received a call to verify if the irradiation duration was adequate.'

If possible, describe the root cause

TotalTimeOfIntervention

20.0