

# NIGHT INCIDENT

## Report



Site

Murcia

Date and time

2024-01-08 05:26

Attended

Phone  Site

Department

Engineering

Scope

Yes  No

System

System description

Describe the incident

The technician said after the module opened the activity inlet valve some drops arrived and the activity inside the horcell increased

Solved?

Yes  No

Derived?

Yes  No

To whom?

Yes - Site manager  Yes - Production manager  Yes - QA  Yes - QC  Yes - QP  Others

Who is other?

Production affected?

No  Yes - Totally cancelled  Yes - Partially cancelled  Yes - Delayed

Any comment?

If possible, describe the solution

Anything

If possible, describe the root cause

The technician did not rinse previous batch

TotalTimeOfIntervention

5.0