

NIGHT INCIDENT



Report

Site

Barcelona

Date and time

2023-05-19 05:00

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Cyclotron - RF

System description

Describe the incident

RF not starting up

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

. Check start-up sequence through the phone with the production technician. Anode OCP error prevents the system to start.

If possible, describe the root cause

Anode over-current error caused by a bad Grid supply voltage (output fuse blown) Planned to replace the tetrode and grid control board since the last PM.

TotalTimeOfIntervention

10.0