

NIGHT INCIDENT



Report

Site

Barcelona

Date and time

2023-06-28 05:50

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

Cyclotron - IS

System description

Describe the incident

IBA IS not working

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

The problem was caused by an overpressure on the target that tripped the IS low current mode.

If possible, describe the solution

If possible, describe the root cause

TotalTimeOfIntervention

60.0