

NIGHT INCIDENT

Report



Site

Oporto

Date and time

2023-07-24 00:00

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

System description

Describe the incident

The new BMR version was put in use without informing engineering in order to give the new instructions to the technician, so the instructions to the pre irradiation changed in the BMR and the technician called to know if she should use or not the new way of pre irradiation.

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site
manager

Yes - Production
manager

Yes -
QA

Yes -
QC

Yes -
QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

If possible, describe the root cause

TotalTimeOfIntervention

5.0