

NIGHT INCIDENT

Report



Site

Venafro

Date and time

2023-08-21 21:27

Attended

Phone Site

Department

E&S

Scope

Yes No

System

System description

Describe the incident

Hydrogen line pressure under 100 KPa read on MFC manometer

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

With GAS ON performed from ServicePC pressure reached 160 KPa

If possible, describe the root cause

Probable internal leak in MFC

TotalTimeOfIntervention

10.0