

NIGHT INCIDENT

Report



Site

Venafro

Date and time

2023-05-16 03:20

Attended

Phone

Site

Department

Production

Scope

Yes

No

System

System description

Describe the incident

Problem during machine tests on Trasis AIO #4227

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

New calibration of vacuum sensor offset

If possible, describe the root cause

Problem to reach the vacuum set point in some steps of the synthesis

TotalTimeOfIntervention

90.0