NIGHT INCIDENT		0-70
Report		A d v a n c e d Accelerator Applications ANovartis Company
Site	Venafro	of to accord failed as
Date and time	2023-05-25 23:51	1
Attended Phone X Site		
Department		
Production		
Scope		
Yes No 🗙		
System		
System description		
Describe the incident		
Beam can't start due to bad setting of magnet pre set current	;	
C 1 10		
Solved? Yes 🗙 No		
Derived?		
Yes No		
To whom?		
Yes - Site Yes - Production	Yes - Yes - Yes	es - Others
manager manager	QA QC O	QP Oulers
Who is other?		
Production affected?		
No X Yes - Totally cancelled Yes - Partially car	ncelled Yes - Delayed	
Any comment?		
If possible, describe the solution		
Reset of correct value of pre set magnet current		
If possible, describe the root cause		
Operator forgot to check the values of most important cyclo	tron parameter before he started irr	adiation
	•	
TotalTimeOfIntervention		
20.0		