

NIGHT INCIDENT



Report

Site

Murcia

Date and time

2022-05-23 03:27

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Cyclotron - S.S. Target

System description

Describe the incident

No current in target 1

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

Impossible to irradiate with target 1. Any production was lost but the activity was reduced due was impossible to do double beam.

If possible, describe the solution

Change to Target 4

If possible, describe the root cause

Carrousel 1 foil disintegration due carrousel problem.

TotalTimeOfIntervention

5.0