

## NIGHT INCIDENT



### Report

Site

Oporto

Date and time

2023-09-12 00:04

Attended

Phone  Site

Department

Engineering

Scope

Yes  No

System

Synthesizers - TRASIS AIO

System description

Describe the incident

The technician misunderstood my request, and I had to set new irradiation parameters because of this misunderstanding.

Solved?

Yes  No

Derived?

Yes  No

To whom?

Yes - Site manager  Yes - Production manager  Yes - QA  Yes - QC  Yes - QP  Others

Who is other?

Production affected?

No  Yes - Totally cancelled  Yes - Partially cancelled  Yes - Delayed

Any comment?

If possible, describe the solution

Put new irradiation parameters and change module

If possible, describe the root cause

TotalTimeOfIntervention

60.0