

NIGHT INCIDENT



Report

Site

Oporto

Date and time

2023-09-14 02:18

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Synthesizers - TRASIS AIO

System description

Describe the incident

Problem with the second run of the trasis. When the production technician put the second run an error appeared: The module does not allow the second run because it appears as aborted, it only gives the option to cancel or not proceed with the second run.

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

Change to another Trasis and do a normal synthesis. On the following day the cassette was removed and I did a wash and dry cycle of the module

If possible, describe the root cause

TotalTimeOfIntervention

60.0