

NIGHT INCIDENT

Report



Site

Oporto

Date and time

2023-10-10 00:12

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

System description

Describe the incident

The calibration hour of the batch on 3Agest and the one in the pdf printed was not the same. They called to know which one to follow. After they understood that the printed one was from the day before.

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site
manager

Yes - Production
manager

Yes -
QA

Yes -
QC

Yes -
QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

If possible, describe the root cause

TotalTimeOfIntervention

2.0