

NIGHT INCIDENT

Report



Site

Oporto

Date and time

2023-11-02 02:30

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

System description

Describe the incident

After the cassette tests was not possible to take control of the AIO-4090.

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site
manager

Yes - Production
manager

Yes -
QA

Yes -
QC

Yes -
QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

To put better the internet cable of the module.

If possible, describe the root cause

TotalTimeOfIntervention

10.0