

NIGHT INCIDENT



Report

Site

Barcelona

Date and time

2024-01-22 00:38

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Distribution - Theodorico

System description

Describe the incident

0:38 When opening the autoclave chamber, water comes out and wets Theo's cell and the paintings below. Technicians are asked to clean the water and test the Theo and auto05 1:09 Theo does not read the vial after filling. I ask you to tilt the sensor with a flat screwdriver so that it better detects the vial. 1:20 The Theo is operational again

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

Cleaning the Theo hot cell and tilting the vial sensor

If possible, describe the root cause

drainage problems in the theodorico autoclave and crashes in the robot

TotalTimeOfIntervention

45.0