

NIGHT INCIDENT



Report

Site

Oporto

Date and time

2024-02-11 23:45

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Cyclotron - IS

System description

Describe the incident

Due to gas flow fault errors, the start of the irradiation was delayed 20 min, so they asked what would be the new irradiation parameters.

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

If possible, describe the root cause

TotalTimeOfIntervention

10.0