

NIGHT INCIDENT



Report

Site

Murcia

Date and time

2024-04-01 05:15

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

Cyclotron - Magnet

System description

Describe the incident

Thermal fuse broke

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

No spare parts available

If possible, describe the solution

Need to change the fuse, is a special american model, so probably is needed to change the base and the fuse to an european with same characteristics

If possible, describe the root cause

TotalTimeOfIntervention

60.0