

NIGHT INCIDENT

Report



Site

Oporto

Date and time

2024-04-10 10:00

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Others - Bunker Door

System description

Describe the incident

Due to late irradiation for test of cyclotron by engineering team the bunker door was unable to open

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

Press the bypass button (red one)

If possible, describe the root cause

TotalTimeOfIntervention

5.0