NICHT INCIDENT



Report

| Site | Barcelona | |
|--|------------------------------------|---------------------|
| Date and time | 2024-05-13 05:55 | |
| | | |
| Attended Phone Site | | |
| Department | | |
| Engineering | | |
| Scope | | |
| Yes No No | | |
| System | | |
| | | |
| System description | | |
| | | |
| Describe the incident | | |
| The temperature of the water cooling is 35 degrees | | |
| Solved? | | |
| Yes No X | | |
| Derived? | | |
| Yes No 🗶 | | |
| To whom? | | |
| Yes - Site Yes - Production manager manager | Yes - QA QC | Yes - QP Others |
| Who is other? | | |
| | | |
| Production affected? | | |
| No Yes - Totally cancelled Yes - Partially can | ncelled Yes - Delayed | |
| Any comment? | | |
| The trainer water cooling system is having some alarms. Corcompany | nsa is working on it and trying to | contact with Traner |
| If possible, describe the solution | | |
| NA | | |
| If possible, describe the root cause | | |
| NA | | |
| TotalTimeOfIntervention | | |

30.0