

NIGHT INCIDENT

Report



Site

Barcelona

Date and time

2024-07-01 00:25

Attended

Phone  Site

Department

Engineering

Scope

Yes  No

System

System description

Describe the incident

2 incidents happened: -The CFL was not working, the panel was not loading -Big issue in the main vaccum system of PETtrace (HVV not opening)

Solved?

Yes  No

Derived?

Yes  No

To whom?

Yes - Site manager  Yes - Production manager  Yes - QA  Yes - QC  Yes - QP  Others

Who is other?

Production affected?

No  Yes - Totally cancelled  Yes - Partially cancelled  Yes - Delayed

Any comment?

If possible, describe the solution

CFL: reboot (solved through the phone) HVV failure: the pneumatic tube of the Lucifer exploded (replaced for a new one)

If possible, describe the root cause

CFL: not clear HVV failure: suspecting aging of the tubing

TotalTimeOfIntervention

120.0