

# NIGHT INCIDENT



## Report

Site

Murcia

Date and time

2024-08-06 11:30

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

Cyclotron - LTF

System description

Describe the incident

The LTF can't fill the Target with water18

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

NA

If possible, describe the solution

Open the connections between water18 and the V4 valve and remove the plastic piece of old ferrule that was blocking the water18 flow

If possible, describe the root cause

A part of the old ferrule was blocking the connectios

TotalTimeOfIntervention

90.0