

# NIGHT INCIDENT



## Report

Site

Barcelona

Date and time

2023-03-02 05:10

Attended

Phone

Site

Department

Scope

Yes

No

System

Cyclotron - He2 gas circuit

System description

Describe the incident

IBA - He cooling not working

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

Somehow the Target was properly selected but the port and the stripper not. This is an uncommon issue.

If possible, describe the root cause

Either software issue or non intentional stripper unselection.

TotalTimeOfIntervention