

NIGHT INCIDENT



Report

Site

Murcia

Date and time

2023-03-14 06:20

Attended

Phone Site

Department

Scope

Yes No

System

Synthesizers - TRASIS AIO

System description

Describe the incident

HPLC error, presion does not achieve 5bars, impossible to retry and continue synthesis due software problem

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

Was possible to continue taking the control in other computer. In the end the batch almost does not have activity. Other batch was planned in other TRASIS AIO

If possible, describe the solution

Start the user in other computer, go to equipment list, select equipment, production, take control

If possible, describe the root cause

NA

TotalTimeOfIntervention