

NIGHT INCIDENT

Report



Site

Oporto

Date and time

2023-03-16 00:24

Attended

Phone

Site

Department

Scope

Yes

No

System

System description

Describe the incident

Pressure transducer of target 1 was not reading.

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

The cables of the pressure transducer were isolated.

If possible, describe the root cause

TotalTimeOfIntervention