## NIGHT INCIDENT



## Report

Site	Barcelona
Date and time	2023-04-11 04:00
Au., J. J	
Attended Phone Site   Site	
Department	
Engineering	
Scope	
Yes No	
System	
Cyclotron - ACU	
System description	
Describe the incident	
After chiller ussues, ACS shows interlock issues on the mast phone (technicians too busy)	ster PC. Not possible to manage the issue through the
Solved?	
Yes No	
Derived?	
Yes No 🗶	
To whom?	
Yes - Site Yes - Production manager	Yes - QA Yes - QP Others
Who is other?	
Production affected?	
No Yes - Totally cancelled Yes - Partially car	ncelled Yes - Delayed
Any comment?	
If possible, describe the solution	
Just check the system and test. No issues found	
If possible, describe the root cause	
Not clear	
TotalTimeOfIntervention	