

NIGHT INCIDENT



Report

Site

Barcelona

Date and time

2023-04-21 04:00

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Cyclotron - ACU

System description

Describe the incident

IBA PLC appears disconnected (link lost)

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

After checking the cables and rebooting the software, the problem remains. After full reboot of the computer the problem was solved. In addition, there was an issue with the transfer valve (non related), the power cable was loose.

If possible, describe the root cause

Not clear

TotalTimeOfIntervention

60.0