

NIGHT INCIDENT



Report

Site

Barcelona

Date and time

2023-05-19 01:30

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

Distribution - Theodorico

System description

Describe the incident

Laptop USB failure (not enough current)

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

Label printer broken and overloading the computer PS

If possible, describe the root cause

Label printer broken and overloading the computer PS

TotalTimeOfIntervention

30.0