NIGHT INCIDENT



Report

		A Novartis Company
Site	Oporto	
Date and time	2023-08-01 01:00	
Attended		
Phone Site Site		
Department		
Engineering		
Scope		
Yes No No		
System		
System description		
Describe the incident		
Instability of the current in the target. They called to know if	they should do something	
insucerity of the current in the tangent They cannot to know in	arey should do someaning.	
Solved?		
Yes No No		
Derived?		
Yes No 🗶		
To whom?		
Yes - Site Yes - Production	Yes - Yes - Yes	()there
manager manager	QA QC QF	·
Who is other?		
Production affected?		
No ■ Yes - Totally cancelled ■ Yes - Partially can	ncelled Yes - Delayed	
Any comment?		
If possible, describe the solution		
We decreased a bit the current and after some time it stabilize	æd.	
If possible, describe the root cause		
The instability was due to the opening of the chamber to solv	we the broken target of the night before	
TotalTimeOfIntervention		
1 OMI I III O III WI VOIMOII		