

## NIGHT INCIDENT

### Report



Site

Meldola

Date and time

2023-10-10 01:26

Attended

Phone

Site

Department

E&S

Scope

Yes

No

System

System description

Describe the incident

Il robot non andava in posizione di riempimento vial

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site  
manager

Yes - Production  
manager

Yes -  
QA

Yes -  
QC

Yes -  
QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

Risolto con riconnessione filo plc

If possible, describe the root cause

Antoine ha staccato involontariamente un filo da sotto la mip

TotalTimeOfIntervention

100.0