

NIGHT INCIDENT

Report



Site

Meldola

Date and time

2023-07-26 01:11

Attended

Phone Site

Department

Production,E&S

Scope

Yes No

System

System description

Describe the incident

Error 'RF system, dpa output match fault' showed up in batch B after 13 minutes of irradiation. Beam has stopped automatically and restarted by operator

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

In this case, restart again the cyclotron normally

If possible, describe the root cause

Not clear, probably cyclotron need a flaps calibration

TotalTimeOfIntervention

20.0