

NIGHT INCIDENT



Report

Site

Murcia

Date and time

2023-10-30 00:46

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

Cyclotron - IS

System description

Describe the incident

Mass flow controller impossible to regulate

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

Use an old massflow controller (that is a little bit defective)

If possible, describe the root cause

Possible electronic damage due radiation

TotalTimeOfIntervention

90.0