

NIGHT INCIDENT



Report

Site

Murcia

Date and time

2024-01-18 06:50

Attended

Phone Site

Department

Engineering

Scope

Yes No

System

Cyclotron - RF

System description

Describe the incident

Motor fault in flap 1 and 2 after to initiate the second target

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

Reset the master PC

If possible, describe the root cause

TotalTimeOfIntervention

20.0