

NIGHT INCIDENT



Report

Site

Barcelona

Date and time

2024-05-06 00:24

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

System description

Describe the incident

The printer of Theodorico vial were not connecting with the pc.

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

The replace the printer and the problema was solved

If possible, describe the root cause

We are not sure if it was the printer or the usb connector of the pc

TotalTimeOfIntervention

30.0