

NIGHT INCIDENT



Report

Site

Murcia

Date and time

2023-04-14 07:30

Attended

Phone

Site

Department

Engineering

Scope

Yes

No

System

Cyclotron - Magnet

System description

Describe the incident

No beam current on target

Solved?

Yes

No

Derived?

Yes

No

To whom?

Yes - Site manager

Yes - Production manager

Yes - QA

Yes - QC

Yes - QP

Others

Who is other?

Production affected?

No

Yes - Totally cancelled

Yes - Partially cancelled

Yes - Delayed

Any comment?

If possible, describe the solution

Reset master pc

If possible, describe the root cause

Possible software bug because the master pc wasn't reset since some weeks ago

TotalTimeOfIntervention

20.0