NICHT INCIDENT



Report

Site	Venafro 2023-08-07 22:19			
Date and time				
Attended				
Phone Site				
Department				
E&S				
Scope				
Yes No No				
System				
System description				
Describe the incident				
RF fault during production due to heater PS fault				
Solved?				
Yes 🗶 No				
Derived?				
Yes No No				
To whom?				
Yes - Site Yes - Production manager manager	Yes - QA	Yes - QC	Yes - QP	Others
Who is other?				
Production affected?				
No Yes - Totally cancelled Yes - Partially can	ncelled	Yes - Delayed		
Any comment?				
If possible, describe the solution				
Stop and restart the RFPG cabinet				
If possible, describe the root cause				
TotalTimeOfIntervention				

60.0