## NICHT INCIDENT



## Report

Site	Site Venafro	
Date and time	2023-12-19 03:20	
		_
Attended		
Phone Site Site		
Department		
Production		
Scope		
Yes No No		
System		
System description		
Describe the incident		
Activity can't be transferred from the synthesizer to the distri	bution system	
Solved?		
Yes No 🗶		
Derived?		
Yes No No		
To whom?		
Yes - Site Yes - Production manager manager	Yes - Yes - Yes - QA QC QC	S - Others
W1 : 4 9		
Who is other?		
Production affected?		
No Yes - Totally cancelled Yes - Partially can	ncelled Yes - Delayed	
Any comment?		
Syringe actuator 3 fault		
If possible, describe the solution		
NA		
If possible, describe the root cause		
Only after technical investigation		
TotalTimeOfIntervention		
20.0		