

NIGHT INCIDENT

Report



Site

Venafro

Date and time

2024-02-21 12:45

Attended

Phone Site

Department

QC

Scope

Yes No

System

System description

Describe the incident

Gluscan 'Validate' injection not conform. The CQ technician asked for a suggestion to solve the issue.

Solved?

Yes No

Derived?

Yes No

To whom?

Yes - Site manager Yes - Production manager Yes - QA Yes - QC Yes - QP Others

Who is other?

Production affected?

No Yes - Totally cancelled Yes - Partially cancelled Yes - Delayed

Any comment?

If possible, describe the solution

Reconditioning of HPLC05

If possible, describe the root cause

Instrument not well conditioned

TotalTimeOfIntervention

20.0