



MAINTENANCE TRACKING TOOL


PETTRACE800

Date:2024-06-12

Country: Iberia	Site: BAR
Intervention:	Programmed maintenance: UBM/CBM <input checked="" type="checkbox"/>
Subsystems:	

PETtrace800 O-Rings analysis

Pins



Pins Data

Pin			
Name the O-Ring	Name and Info of the O-Ring		Name the O-Ring
	Name of O- Ring	Parameter	
(1) Target port o-ring T1	O-Ring 1	1,2,3	3241
Explain The Intervention			
Photos			
4_pin .jpg			

Pin			
Name the O-Ring	Name and Info of the O-Ring		Name the O-Ring
	Name of O- Ring	Parameter	
(1)Target port o-ring T2	O-Ring 1	1,2,3	other test num 1
Explain The Intervention			
67			
Photos			

Pin			
Name the O-Ring	Name and Info of the O-Ring		Name the O-Ring
	Name of O- Ring	Parameter	
(2) BEV o-ring T2	O-Ring 1	1,2,3	56
Explain The Intervention			
34			
Photos			

Pin			
Name the O-Ring	Name and Info of the O-Ring		Name the O-Ring
	Name of O- Ring	Parameter	
(3) BEV internal o-ring T4	O-Ring 2	4,5,6	54
Explain The Intervention			
54			
Photos			

Pin			
Name the O-Ring	Name and Info of the O-Ring		Name the O-Ring
	Name of O- Ring	Parameter	
(6) O-ring DN40 RV/RV-elbow	O-Ring 2	4,5,6	df
Explain The Intervention			
Photos			
dfsdf_pin_.jpg			