

# NIGHT INCIDENT



## Report

Site

Barcelona

Date and time

2023-01-30 02:12

Attended

Phone  Site

Department

Engineering

Scope

Yes  No

System

Cyclotron - WCS

System description

Describe the incident

“QIA1 high cond” Alarm in the WCS Assist production technician regulating the WCS to reduce the conductivity level and remove the alarm. Problems also in the target activation due to this issue. After the regulation, the conductivity went down and the system worked fine. WCS to be checked in the morning.

Solved?

Yes  No

Derived?

Yes  No

To whom?

Yes - Site manager  Yes - Production manager  Yes - QA  Yes - QC  Yes - QP  Others

Who is other?

Production affected?

No  Yes - Totally cancelled  Yes - Partially cancelled  Yes - Delayed

Any comment?

If possible, describe the solution

Regulation of the WCS

If possible, describe the root cause

TBD

TotalTimeOfIntervention

5.0