NIGHT INCIDENT



Report

Site	Venafro	
Date and time	2023-10-24 01:30	
Attended Phone Site		
Department		
E&S		
Scope		
Yes No X		
System		
System description		
ojouni discription		
D 7 4 : 11 /		
Describe the incident Stop cyclo at 120 minutes of beam		
Stop cyclo at 120 minutes of ocam		
Solved?		
Yes No No		
Derived?		
Yes No No		
To whom?		
Yes - Site Yes - Production manager manager	Yes - QA QC	Yes - Others
Who is other?		
Production affected?		
No Yes - Totally cancelled Yes - Partially car	rcelled Yes - Delayed	
Any comment?		
If possible, describe the solution		
Wrong set of Max irradiation time		
If possible, describe the root cause		
Na		
TotalTimeOfIntervention		