



**MAINTENANCE TRACKING TOOL**  
**PETTRACE800**

Date:2023-09-28

<b>Country:</b> Germany	<b>Site:</b> MUN
<b>Intervention:</b>	Programmed maintenance: UBM/CBM <input checked="" type="checkbox"/>
<b>Subsystems:</b>	

**PRE-MAINTENANCE**

**Registration Date:** 2023-09-2000  
**Gas flow(sccm):** 1.0

**TPG Settings Verifications**

	Low limit (x10-)	High limit (x10-)
<b>Piranni 1 (TPG300 A1):</b>	1.0	2.0
<b>Piranni 2 (TPG300 A2):</b>	3.0	4.0
<b>Penning:</b>	5.0	6.0

**Notes**

notas
-------

Gauge number	Pressure (x10-) without gas	Pressure (x10-) with gas
<b>A1:</b>	A1	A2
<b>A2 Under Range:</b>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<b>A2:</b>		
<b>B1:</b>	B1	B2

**System software**

Subsystem	Version
<b>Master:</b>	Master
<b>ACS:</b>	1
<b>Service System:</b>	2
<b>Manager:</b>	3
<b>Informix (only applicable to SUN-Master Station):</b>	4

Comments

comentario

Paper Burn Before PM

Image



photo2



Image



photo2



photo1



photo2



